



telegram

TBB118(1025)(2-144076E248)PD 09/05/73 1025

ICS IPMBNGZ CSP

2057298316 TDBN ATHENS AL 55 09-05 1025A EST

FON 4045264503

U S ATOMIC ENERGY COMMISSION

230 PEACHTREE ST NORTHWEST

ATLANTA GA 30303

SUBJECT BFNP-BFAO 738. DURING ROUTINE TESTING OF THE HPCI WITH
AUXILIARY STEAM AT 1PM SEPTEMBER 4 STEAM VALVE FCV-73-16 WHICH
IS THE STEAM SUPPLY VALVE TO THE TURBINE FAILED TO OPERATE PRELIMINAR
Y INVESTIGATION SHOWED THE TROUBLE TO BE IN THE VALVE GEAR BOX
PLANT CONDITION DID NOT REQUIRE THE HPCI TO BE OPERABLE

TENNESSEE VALLEY AUTHORITY H J GREEN BROWN'S FERRY NUCLEAR
PLANT

BF-1201 (RS-66)

8308300053 730912
PDR ADOCK 05000259
S PDR