



Telegram

BND106(1004)(1-007727C212)PD 07/31/73 1002

ICS IPMVEIC MVN

03038 (03228) TDVE MORRIS ILL 93 07-30 330P CDT

FON 3128582660

BOYCE BRIER DIRECTOR DIV OF COMPLIANCE

REGION E US ATOMIC ENERGY COMMISSION 799

ROOSEVELT RD GLEN ELLYN IL 60137

SUBJECT DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH MR F MAURA OF YOUR OFFICE

AT 1030 HOURS THIS DATE CONCERNING FAST CLOSURE TIME ON 1B

MAIN STEAM ISOLATION VALVE. ON 7/29/73 DURING A UNIT STAT UP 1B MSIV

WAS TIMED AND FOUND TO HAVE A CLOSURE TIME OF 2.6 SECONDS.

CABLE 3.7.1 OF TECHNICAL SPECIFICATIONS REQUIRES A CLOSURE TIME OF BE

T-

SF-1201 (RS-69)


BETWEEN 3 AND 5 SECONDS

UNTIL PROBLEMS CAN BE CORRECTED, MSIVS 1 B AND 2 B WILL REMAIN CLOSED

W P WARDEN SUPERINTENDENT DRESDEN NUCLEAR POWERSTATION

0310200367 730731
PDR ADOCK 05000249
S PDR

SF-1201 (RS-69)



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

006
SEB ZEB

TELEPHONE
(312) 858-2660

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files

C. Incident Notification From: Commonwealth Edison Co. DPR-25
(Licensee & Docket No. (or License No.))

Transmittal Date : August 6, 1973

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files