



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

10CFR50.54(a)(3)

E. T. Boulette, PhD
Senior Vice President — Nuclear

June 21, 1995
BECO Ltr #95-066

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

License DPR-35
Docket 50-293

Annual Report of Changes to the
BOSTON EDISON QUALITY ASSURANCE PROGRAM DESCRIPTION

As required by 10CFR50.54(a)(3), Boston Edison submits the annual summary of changes made to the Boston Edison Quality Assurance Program Description as listed in the Boston Edison Quality Assurance Manual (BEQAM), Volume II. This report covers the period from July 1994 through June 1995.

During this reporting period, there have been no changes in the Quality Assurance Program Description previously approved by the NRC.


E.T. Boulette

ETB/GGW/nas/Rap95/BEQAM95

cc: Mr. R. Eaton, Project Manager
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
Mail Stop: 14D1
U.S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 02852

Chief of Materials Section
Division of Reactor Safety
U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station

9506280337 950621
PDR ADOCK 05000293
R PDR

270047

9004.1/0