



Public Service Company of Colorado
P. O. Box 361, Platteville, Colorado 80651



May 13, 1976
Fort St. Vrain
Unit No. 1
P-76107

Mr. E. Morris Howard, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Howard:

Enclosed please find a copy of Unusual Event Report No. 50-267/75/03A, Supplement and Unusual Event Report No. 50-267/75/03B, Supplement, submitted per the requirements of the Technical Specifications.

Also please find enclosed one copy of the Licensee Event Report for Unusual Event Report No. 50-267/75/03A and one copy of the Licensee Event Report for Unusual Event Report No. 50-267/75/03B.

Very truly yours,

Frederic E. Swart
Superintendent, Nuclear Production
Fort St. Vrain Nuclear
Generating Station

FES/alk

cc: Mr. Roger S. Boyd

8311020438 760513
PDR ADOCK 05000267
S PDR

4919