

P.O. Box 361, Platteville, Colorado 80651

February 13, 1976
Fort St. Vrain
Unit No. 1
P-76044

Mr. E. Morris Howard, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
Suite 1000
Arlington, Texas 76012

Ref: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Howard:

Enclosed please find a copy of Abnormal Occurrence Report No. 50-267/
76/04, Preliminary, submitted per the requirements of the Technical
Specifications.

Also, please find enclosed one copy of the Licensee Event Report for
Abnormal Occurrence Report No. 50-267/76/04.

Very truly yours,

Frederic E. Swart
Superintendent, Nuclear Production
Fort St. Vrain Nuclear
Generating Station

FES/dme

cc: Mr. Roger S. Boyd

8311080587 760213
PDR ADDCK 05000267
S PDR