

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 0010 F S V I LICENSE NUMBER: 00-000000-000 LICENSE TYPE: 41120 0

CONT: 011 CATEGORY: M 53 REPORT TYPE: 7 53 REPORT SOURCE: 4 60 DOCKET NUMBER: 050-0267 53 83 EVENT DATE: 072676 74 75 DATE: 072676 80

EVENT DESCRIPTION

03 7 8 9 Operator was running recirculator from section.
03 7 8 9 Opened containment tank drain valve. Tripped 11-u-
04 7 8 9 later 10 and allowed primary coolant into
05 7 8 9 Reactor Building. Closed valve and restricted
06 7 8 9 building access. (AO 7/26/76)

SYSTEM CODE: 07 7 8 9 10 11 CAUSE CODE: 5 11 COMPONENT CODE: V X X X X X 12 17 PRIME COMPONENT SUPPLIER: 3 43 COMPONENT MANUFACTURER: 9 9 9 44 47 VIOLATION: V 48

CAUSE DESCRIPTION

08 7 8 9 Operator failed to follow established clearance
09 7 8 9 operator reprimanded and clearance procedure
10 7 8 9 has been changed.

FACILITY STATUS: 11 7 8 9 10 11 12 13 % POWER: 0 1 1 10 12 13 OTHER STATUS: 44 45 METHOD OF DISCOVERY: A 45 46 DISCOVERY DESCRIPTION: N/A

FORM OF ACTIVITY RELEASED: 12 7 8 9 10 11 12 13 CONTENT OF RELEASE: V 10 11 AMOUNT OF ACTIVITY: Not measured 44 45 LOCATION OF RELEASE: Vent to Reactor Building 46 47 48

PERSONNEL EXPOSURES

NUMBER: 13 7 8 9 10 11 12 13 TYPE: 3 12 13 DESCRIPTION: Not detectable by whole body counts.

PERSONNEL INJURIES

NUMBER: 14 7 8 9 10 11 12 13 DESCRIPTION: N/A

OFFSITE CONSEQUENCES

15 7 8 9 10 11 12 13 None

LOSS OR DAMAGE TO FACILITY

TYPE: 16 7 8 9 10 11 12 13 DESCRIPTION: N/A

PUBLICITY

17 7 8 9 10 11 12 13 N/A

ADDITIONAL FACTORS

18 7 8 9 10 11 12 13 Airborne activity in Reactor Building increased

19 7 8 9 10 11 12 13 but value not measured

NAME: H. W. Hilliard, Jr. PHONE: (303) 785-2553

8311110107 770713
PDR ADDCK 05000267
S PDR