



Tennessee Valley Authority, Post Office Box 2000, Soddy-Daisy, Tennessee 37379

June 22, 1995

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE - DPR-77 - LICENSEE EVENT REPORT  
(LER) 50-327/95005

The enclosed LER provides details concerning the failure to perform the required valve stroke time test on four containment isolation valves following maintenance on their power circuitry.

This event is being reported in accordance with 10 CFR 50.73(a)(2)(i) as a condition prohibited by technical specifications.

Sincerely,



R. J. Adney  
Site Vice President

Enclosure  
cc: See page 2

280024

9506300246 950622  
PDR ADDCK 05000327  
S PDR

IE22  
11

U.S. Nuclear Regulatory Commission

Page 2

June 22, 1995

cc (Enclosure):

INPO Records Center  
Institute of Nuclear Power Operations  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957

Mr. D. E. LaBarge, Project Manager  
U.S. Nuclear Regulatory Commission  
One White Flint, North  
11555 Rockville Pike  
Rockville, Maryland 20852-2739

NRC Resident Inspector  
Sequoyah Nuclear Plant  
2600 Igou Ferry Road  
Soddy-Daisy, Tennessee 37379-3624

Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323-2711