

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

June 22, 1995
ST-HL-AE-5112
File No: T07.03
10CFR50.55a

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1


Docket No: STN 50-498

Unit 1 Fifth Refueling Outage

Inservice Inspection Summary Report For Repairs and Replacements

The Unit 1 fifth refueling outage (1RE05) Inservice Inspection Summary Report for Repairs and Replacements performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station is enclosed. This summary report includes the period from completion of the fourth refueling outage (December 31, 1992) to completion of the fifth refueling outage (April 14, 1995) for Unit 1.

If you should have any questions, please contact Mr. K. J. Taplett at (512)972-8416 or me at (512)972-8787.



T. H. Cloninger
Vice President,
Nuclear Engineering

APP/pas
Attachments: Per attached index

300026

Project Manager on Behalf of the Participants in the South Texas Project

MISC-95/95-171-001

9506300314 950622
PDR ADOCK 05000498
Q PDR

AD47.1

Houston Lighting & Power Company
South Texas Project Electric Generating Station

ST-HL-AE-5112
File No.: T07.03
Page 2

c:

*Leonard J. Callan
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Thomas W. Alexion
Project Manager
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001 13H15

*David P. Loveless
Sr. Resident Inspector
c/o U. S. Nuclear Regulatory Comm.
P. O. Box 910
Bay City, TX 77404-0910

J. R. Newman, Esquire
Morgan, Lewis & Bockius
1800 M Street, N.W.
Washington, DC 20036-5869

K. J. Fiedler/M. T. Hardt
City Public Service
P. O. Box 1771
San Antonio, TX 78296

J. C. Lanier/M. B. Lee
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

G. E. Vaughn/C. A. Johnson
Central Power and Light Company
P. O. Box 2121
Corpus Christi, TX 78403

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61067
Houston, TX 77208

Institute of Nuclear Power
Operations - Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

*U. S. Nuclear Regulatory Comm.
Attn: Document Control Desk
Washington, D. C. 20555-0001

J. R. Egan, Esquire
Egan & Associates, P.C.
2300 N Street, N.W.
Washington, D.C. 20037

* Above copies distributed without Attachments except as noted by asterisk (*).

INDEX OF ATTACHMENTS

1. Cover Sheet
2. 1RE05 Inservice Inspection Summary Report for Repairs and Replacements
(16 Pages)