

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

W. L. STEWART  
VICE PRESIDENT  
NUCLEAR OPERATIONS

March 2, 1984

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
Attn: Mr. James R. Miller, Chief  
Operating Reactors Branch No. 3  
Division of Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Serial No. 385C  
NO/JHL:acm  
Docket Nos. 50-338  
50-339  
License Nos. NPF-4  
NPF-7


Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY  
NORTH ANNA POWER STATION UNIT NO. 2  
LOW PRESSURE TURBINE DISC CRACKING REPORT

In our letter dated August 10, 1983 (Serial No. 385B) Vepco stated that the submittal date for the North Anna Unit No. 2 low pressure turbine disc cracking report would be March 1, 1984.

Vepco has recently contacted Southwest Research to determine if the report submittal date of March 1, 1984 was still on schedule. Southwest Research said that they had encountered a delay in receipt of the dissected disc. This delay had an impact on their completion of the analysis. The present schedule is to submit the North Anna Unit No. 2 low pressure turbine disc cracking report by March 30, 1984.

Very truly yours,

  
W. L. Stewart

cc: Mr. James P. O'Reilly  
Regional Administrator  
Region II

Mr. M. W. Branch  
NRC Resident Inspector  
North Anna Power Station

8403080071 840302  
PDR ADOCK 05000339  
P PDR

Acc'd  
1/0