



# Telegram

753P EDT OCT 25 71 AB259 KA328

AA K FEA076NL PDF TDFE HARTSVILLE SOCAR 25

JOHN DAVIS

AEC DIVN OF COMPLIANCE REGION TWO 230 PEACHTREE ST ATLANTA

*DIRGA*

ON MONDAY OCT 25 RADIATION MONITOR 4-19 ON THE STEAM GENERATOR BLOW DOWN ATARMED. BY ISOLATING THE STEAM GENERATORS INDIVIDUALLY IT WAS DETERMINED THAT A PRIMARY TO SECONDARY LEAK OF APPROXIMATELY ONE GALLON PER HOUR HAD DEVELOPED IN "A" STEAM GENERATOR. SECONDARY CHEMICAL ANALYSIS SHOWED ACTIVITY TO BE 2.32 X TEN TO THE MINOR FIVE MICROCSRIES PER CUBIC CENT. GRLOSS IODINE WHICH IS WELL BELOW LIMITS SET BY OUR TECHNICAL SPECIFICATIONS. A CHEMIST FROM WESTINGHOUSE INC WILL ARRIVE ON SITE TUESDAY OCTOBER 26 TO ASSIST PLANT PERSONNEL IN EVALUATING THIS LEAK. THIS REPORT IS IN ACCORDANCE WITH THEHNICAL SPEFICIATIONS 6.6.1C PREEVIOUSLY REPORTED BY TELEPHONE TO MR DON KIRFPATRICK ON

SF-1201 (R5-69)

western union

# Telegram

OCT 25 1971

J B MCGIRT

CAROLINA POWER AND LIGHT COMPANY

H B ROBINSON PLANT

HARTSVILLE SC

2.32 X TEN 26 6.6.1C 25 1971  
(71\$).

*IS/GHX/Staff 11/4/71*

B403090042 711027  
PDR ADOCK 05000261  
S PDR

OCT 25 15 14 BN 11

VLF VHF CV  
COMPLIANCE II  
D 2 1 1 C

SF-1201 (R5-69)

Copy sent PDR