

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

February 22, 1984

APPP-28917-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 83-81
A 50.55(e) Potentially Reportable Deficiency Relating To
Schedule 160 SS Pipe From Gulfalloy, Inc., Contains A
Manufacturing Defect Which Violates Minimum Wall Thickness
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between J. Eckhart and K. C.
Parrish on November 28, 1983
(B) ANPP-28473, dated December 20, 1983 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
February 28, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by April 17, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr.

E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:ru

cc: See Page Two

8403090087 140222
PDR ADOCK 03000528
S PDR

1E27
1/0

Mr. T. W. Bishop
DER 83-81
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
L. A. Souza
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339