

Carolina Power & Light Company

Raleigh, North Carolina 27602

August 27, 1971

50-261



Dr. Peter Morris
Division of Reactor Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545

H. B. ROBINSON STEAM ELECTRIC PLANT
UNIT NO. 2
LICENSE DPR-23

Dear Dr. Morris:

In accordance with paragraph 6.6.1.C, Technical Specifications, H. B. Robinson Unit No. 2, it is reported that a leak developed in the main coolant sample cooler on August 22, 1971 allowing primary coolant to leak into the component cooling system. The cooler was isolated and will be replaced. Maximum activity in the component cooling system was 7.65×10^{-5} micro curies per cubic centimeter.

*IS/ JAK/ Staff 9/10/71
RHE
LK
CAP*

Yours very truly,

[Signature]
E. E. Utley
Manager
Generation & System Operations

NBB/sfb

cc: Mr. G. P. Beatty
Mr. N. B. Bessac
Mr. C. D. Barham

INquire Rpt 8-23-7

8403090296 710827
PDR ADDCK 05000261
S PDR

1 4439

COPY SENT REGION

3945