

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23883

October 17, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by teletype of an Abnormal Occurrence that was noted on October 11, 1975 at Surry Nuclear Power Station. Performance of the Type A containment leakage rate test revealed that the Unit No. 1 containment leakage rate was greater than the acceptance criteria specified in Appendix J of 10CFR50.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Manager

54-280

8403090402 751028
PDR ADOCK 05000280
S PDR