

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station
P.O. Box 315
Surry, Virginia 23683

July 21, 1975

Director of Regulatory Operations
230 Peachtree Street
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on July 20, 1975 at Surry Nuclear Power Station.

With Unit 2 operating at 100% power, it was found that a low level amplifier had failed, causing one ΔT protection channel to be unconservative.

Tyndall Roney
E. H. Sweeney, Jr.
Manager

8403120343 750724
PDR ADOCK 05000281
S PDR

54-281
inquiry

Letter to N. C. Moseley from Virginia Electric and Power Company dated July 21, 1975.

Letter to N. C. Moseley from Virginia Electric and Power Company dated July 7, 1975.

Letter to N. C. Moseley from Virginia Electric and Power Company dated July 1, 1975.

DISTRIBUTION:

50-281

H. D. Thornburg, IE

IE:HQS (4)

Office of Standards Development

Central Files

Division of Reactor Licensing (4)

PDR

Local PDR

NSIC

TIC

STATE

50-281
inquiry