



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429  
March 9, 1984

FILE: B09-13510C  
SERIAL: BSEP/84-0549

Mr. James P. O'Reilly, Administrator  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2  
LICENSE NO. DPR-62  
DOCKET NO. 50-324  
LICENSEE EVENT REPORT 2-84-1

Dear Mr. O'Reilly:

In our letter of February 22, 1984, (Serial BSEP/84-0441) Carolina Power & Light Company notified you of a potentially reportable event which was still being investigated (E41-LS-N003 vent line problem). The investigation and evaluation have been completed, and this event has been determined to be not reportable under 10CFR50.73, as this failure falls under the single component failure criteria. This number will be assigned a future event for reporting purposes.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/kal/LETDR1

cc: Mr. R. C. DeYoung  
NRC Document Control Desk

8403130078 840309  
PDR ADOCK 05000324  
S PDR

IE22  
1/0