



MISSISSIPPI POWER & LIGHT COMPANY

*Helping Build Mississippi*

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

March 5, 1984

3 49:39

NUCLEAR PRODUCTION DEPARTMENT

U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Special Report 84-009/0 -  
Smoke Detector Covered for  
Planned Maintenance  
AECM-84/0118

On January 21, 1984, a smoke detector in Zone 2-4 was covered for planned maintenance activities. The detector, located in the RHR "A" Piping Room on elevation 119 feet of the Auxiliary Building, was covered due to welding in the room. The zone was reset and restored to operability on February 6, 1984.

Fire watches were established in accordance with Technical Specification 3.3.7.9. This is reported as a Special Report pursuant to Technical Specification 6.9.2 since the fourteen (14) day Limiting Condition for Operation (LCO) was exceeded. The event had no effect on the health and safety of the public and did not constitute a threat to plant safety. This is a final report.

Yours truly,

L. F. Dale  
Manager of Nuclear Services

EBS/SHH:sad

cc: (See Next Page)

8403130253 840305  
PDR ADOCK 05000416  
S PDR

Member Middle South Utilities System

OFFICIAL COPY

JK22

1/0

MISSISSIPPI POWER & LIGHT COMPANY

AECM-84/0118

Page 2

cc: Mr. J. B. Richard  
Mr. R. B. McGehee  
Mr. T. B. Conner  
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555