

EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
0	9	I	A	B	B	I	N	S	T	R	U	T	Z
9		10		11		12		13		14		15	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE				REPORT TYPE		REVISION NO.			
8	1	030		03				X		1			
21		22		23		24		25		26			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.	
G	F	Z	Z	00000		N		Y		L		R335	
18		19		20		21		22		23		24	
25		26		27		28		29		30		31	
PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											
32		33											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION								
1	5	E	28	1	0	0	29	NA	30	B	31	Routine Test	32

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		37	7	38
				NA

PERSONNEL INJURIES					
NUMBER			DESCRIPTION		
1	8	000	(40)		NA

8 9 11 12
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
1 9 Z (42) NA
8403130450 840305
PDR ADPOCK 050000000

8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N 4A NA
S 000000318
PDR
NRC USE ONLY

NAME OF PREPARER R. B. Sydnor

PHONE: 301-260-4014

8403130450 840305
PDR ADDOCK 05000318
S PDR

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

March 5, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC. 20555


Docket No. 50-318
License No. DPR-69

Dear Sir:

The attached supplemental report to LER 81-30/3X, Revision 1, is being sent to you as required by 10 CFR 50.73.

Should you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,



L. B. Russell
Plant Superintendent

LBR:RBS:mst

cc: Dr. T. E. Murley
Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IE22
1/1