

# Duquesne Light Company

Beaver Valley Power Station  
P.O. Box 4  
Shippingport, PA 15077-0004  
(412) 393-5206  
(412) 643-8069 FAX

GEORGE S. THOMAS  
Division Vice President  
Nuclear Services  
Nuclear Power Division

August 1, 1995

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555-0001


**Subject: Beaver Valley Power Station, Unit No. 2  
Docket No. 50-412, License No. NPF-73  
Fifth Refueling Outage Inservice Inspection Report**

This letter forwards the Inservice Inspection Ninety-Day report on ASME Class 1, 2, and 3 components examined during the fifth refueling outage at Beaver Valley Unit No. 2. The ASME Boiler and Pressure Vessel Code, Section XI, Article IWA-6230 requires that an inservice inspection report be submitted to the enforcement and regulatory authority having jurisdiction at the plant within ninety days after completion of an inservice inspection. The recent inservice inspection term at Beaver Valley Unit No. 2 ended on May 7, 1995.

These examinations are part of Interval 1, Period 3 of the Unit No. 2 ISI schedule. The inservice inspections were performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code, 1983 Edition through Summer 1983 Addenda, using Code Case N-408 for Class 2 piping welds.

If you have any questions, please contact Mr. Steve Sevvick at (412) 393-5211.

Sincerely,



George S. Thomas

## Attachment

- c: Mr. L. W. Rossbach, Sr. Resident Inspector
- Mr. J. L. Martin, NRC Region I Administrator
- Mr. D. S. Brinkman, Sr. Project Manager

9508140303 950801  
PDR ADOCK 05000412  
Q PDR

ADH