



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

34 MAR 14 A 8:37 March 9, 1984

NUCLEAR PRODUCTION DEPARTMENT

U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N.W., Suite 2900
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Special Report 84-012/0 -
Nonconforming Fire Doors
AECM-84/0158

On February 1, 1984, a special fire door inspection was conducted in which 147 doors in the Auxiliary Building and Control Building were determined not to be in compliance with the original specification requirements. The nonconformances consist of door modifications, door-to-frame gaps in excess of specified tolerances, and Underwriter Laboratory labels missing from the doors.

Fire watches were established in the affected areas as required by Technical Specification 3.7.7. The deficiencies are documented on plant Material Nonconformance Reports (MNCRs) 00117-84, 00118-84, and 00119-84.

Overly Manufacturing Company and Richards Wilcox are the manufacturers of special doors; i.e., air, water, pressure tight or bullet resistant. Both suppliers have performed independent inspections and have supplied information identifying the necessary actions required to recertify the doors.

The hollow-metal type doors were supplied by Williamsburg Steel Products Company. Since the company is no longer in business, MP&L has contacted Underwriters Laboratories concerning recertification of these doors. To date a commitment from Underwriters Laboratories has not been received.


8403190331 840309
PDR ADDCK 05000416
S PDR

AB1

OFFICIAL COPY
JAZZ 10

An expected date for completion of the recertification and restoration of the doors cannot be made at this time. This Special Report is therefore submitted as an interim report. An update is expected to be submitted by May 31, 1984.

Yours truly,



L. F. Dale
Manager of Nuclear Services

EBS/SHH:lm

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. T. B. Conner
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Document Control Clerk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555