

Duquesne Light Company

Beaver Valley Power Station
P.O. Box 4
Shippingport, PA 15077-0004
(412) 393-5206
(412) 643-8069 FAX

GEORGE S. THOMAS
Division Vice President
Nuclear Services
Nuclear Power Division

March 2, 1995

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

Subject: Beaver Valley Power Station, Unit No. 1
Docket No. 50-334, License No. DPR-66
Tenth Refueling Outage Steam Generator Return to Power Report


- References:
1. Safety Evaluation by the Office of Nuclear Reactor Regulation Related to Amendment No. 184 to Facility Operating License No. DPR-66 Duquesne Light Company Beaver Valley Power Station Unit No. 1 Docket No. 50-334.
 2. Letter from G. S. Thomas (Duquesne Light Company) to U. S. Nuclear Regulatory Commission, "Response to Information Request Dated December 1, 1994," December 13, 1994.

Enclosed is a copy of the "Interim Plugging Criteria Return to Power Letter Report," which is provided to satisfy the requirements of Technical Specification 4.4.5.5.e and Reference 1, paragraph 2.6. This report also provides documentation associated with commitments identified in Reference 2 for items 1, 2, 3, 4, 6, 7, 8, 9, 10 and 14. A copy of WCAP-14277, "SLB Leak Rate and Tube Burst Probability Analysis Methods for ODS/CC at TSP Intersections," which is referenced in the Letter Report, is also enclosed.

Three tubes were pulled to support interim tube plugging criteria implementation as required by Reference 1 and Reference 2, item 5. These tubes provide eight tube support plate intersections for laboratory analyses. The results of the analyses will be provided to the NRC within ninety days following restart from the tenth refueling outage. No leaking tubes were identified during this steam generator examination.

If you have any questions regarding the attached information, please contact Mr. G. A. Kammerdeiner, Nuclear Engineering Department, at (412) 393-5677.

Sincerely,


George S. Thomas

130054

Enclosures

cc: Mr. L. W. Rossbach, Sr. Resident Inspector
Mr. T. T. Martin, NRC Region I Administrator
Mr. G. F. Edison, Sr. Project Manager
9503130143 950302
PDR ADDCK 03000334
P PDR

A001
111