



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

MURRAY R. EDELMAN

VICE PRESIDENT
NUCLEAR

March 9, 1984

PY-CEI/NRR-0099 L

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Perry Nuclear Power Plant
Docket Nos. 50-440; 50-441
Operating Shift Experience

Dear Mr. Denton:

Enclosed are tables reflecting the nuclear power plant experience for operating shift positions at the Perry Nuclear Power Plant. The two sets of tables reflect current staffing experience levels and the level projected at the time of fuel load for Unit 1, now scheduled for June 1985. The information provided is based on present operators participating on-shift, in license training or at an operating plant from now until fuel load. At the present time, we plan to meet the experience criteria without the use of consultants as advisors.

Experience information is also included for the Shift Technical Advisors. Four of these individuals are currently participating in the Unit 2 Susquehanna Steam Electric Station power ascension test program. These STA's will be licensed as Senior Operators and assigned on shift to fulfill Hot Participation experience requirement.

Should you have any further questions, please contact us.

Very truly yours,

Murray R. Edelman
Vice President
Nuclear

MRE:kay

cc: H. Thompson
J. Stefano
J. Silberg, Esq.
M. Gildner

8403190391 840309
PDR ADQCK 05000440
A PDR

MOO3
11

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

OPERATING SHIFT EXPERIENCE

JOB TITLE: Shift Supervisors
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	36/36	0/0				
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0				
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	30/30	0/0	0/0	25/25	0/0				
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0				
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PPHS) (OTHER)	0.50 0.25	36 MONTHS	14/7 0/0	0/0 72/18	12/6 35/8.8	26/13 24/6	42/21 0/0	50/25 0/0				
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	0/0 1/3	0/0 .2/.5	.6/3 1/3	.6/3 1.2/3.6	.6/3 1/3	0/0 1/3				
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 10/5	0/0 0/0	0/0 6/3	2/1.5 6/3	0/0 2/1	0/0 12/6				
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	0/0	0/0	5/2.5	5/2.5	0/0	0/0				
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	31/12	.5/.4	.5/.4	12/9	0/0				
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	63/12	74/12	78/12	80/12	22/5.5	76/12				
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0				
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	# * 9	 3	# 6	# * 10	* 1	 0				
TOTAL NUCLEAR PLANT EXPERIENCE:			36	75.6	44.7	55	104.5	46				
HOT PARTICIPATION EXPERIENCE												
TIME * 20% PWR/R/R (YKS)			130	2	2	264						
STARTUP & SHUTDOWN (YES/NO)			Yes	No	Yes	Yes						
MONTHS ON SHIFT			30	.5	.5	61						

* SRO Upgrade Program to
train as an STA
Associated Degree

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO) AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors unless some other method is used.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

JOB TITLE: Unit Supervisors
(NOTE 2)NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PWMS) (OTHER)	0.50 0.25	36 MONTHS	94/36 24/0	18/9 36/9	0/0 0/0	2/1 46/11.5	74/36 0/0	0/0 0/0	0/0 0/0	36/18 30/7.5	0/0 0/0	
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 1.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.6/8 0/0	1.6/8 0/0	.25/ 1/3	1.6/8 0/0	1.2/6 0/0	.6/3 1/3	.6/3 1/3	1.6/8 0/0	.6/3 1/3	
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	2/1.5 12/6	2/1.5 8/4	0/0 0/0	2/1.5 3/1.5	0/0 10/5	2/1.5 3/1.5	2/1.5 12/6	2/1.5 6/3	0/0 0/0	
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	5/2.5	5/2.5	0/0	5/2.5	0/0	5/2.5	5/2.5	0/0	5/2.5	
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	.5/.4	1.5/ 1.1	1.5/ 1.1	0/0	1.5/1.1	1.5/1.1	.5/.4	1.5/1.1	5/3.8	
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	35/8.8	24/6	25/6.3	28/7	40/10	50/12	44/11	42/10.5	70/12	
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	* # 12	* 5	 12	* 2	* 3	* 3	* 3	* 8	* 4	
TOTAL NUCLEAR PLANT EXPERIENCE:			75.6	46.1	23.7	35	61.6	27.6	30.4	57.6	28.3	
HOT PARTICIPATION EXPERIENCE												
TIME > 20% PWR/BWR (WKS)			2	6	6		6	6	2	6	8	
STARTUP & SHUTDOWN (YES/NO)			No	Yes	No		Yes	No	No	Yes	No	
MONTHS ON SHIFT			0.5	1.5	1.5		1.5	1.5	0.5	1.5	5	

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. To not plan to use shift advisors unless more info.

*SRO Upgrade Program to
train as an STA
Associates Degree

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

JOB TITLE: Supervising Operators
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PPWS) (OTHER)	0.50 0.25	36 MONTHS	0/0 52/13	18/9 35/8.8	0/0 96/24	2/1 44/11	0/0 0/0	0/0 84/21	49/24 0/0	2/1 48/12	0/0 46/11.5	25/12.5 0/0
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1/5 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	.6/3 1/3	1.6/8 0/0	1/5 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 0/0	2/1.5 3/1.5	2/1.5 10/5	2/1.5 10/5	0/0 2/1	2/1.5 11/5.5	0/0 2/1	1/1.75 3/1.5	0/0 0/0	2/1.5 2/1
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	0/0	5/2.5	5/2.5	0/0	0/0	5/2.5	0/0	5/2.5	5/2.5	5/2.5
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	30/7.5	8/2	23/5.8	24/6	54/12	21/5.3	22/5.5	19/4.8	57/12	20/5
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	1	0	0	0	* 5	1	* 5	1	0	* 4
TOTAL NUCLEAR PLANT EXPERIENCE:			26.5	33.3	46.8	32.5	24	44.8	40.5	32.05	34	34.5
HOT PARTICIPATION EXPERIENCE												
TIME x 20% PWR/BWR (WKS)												
STARTUP & SHUTDOWN (YES/NO)												
MONTHS ON SHIFT												

*SRO Upgrade Program to
train as an STANOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"

CHECK ONE OF THE FOLLOWING:

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use a. or b. advisors unless now under contract.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

OPERATING SHIFT EXPERIENCE

JOB TITLE: Supervising Operators
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
5. NAVY (MILITARY) NUCLEAR (PD, EWS, ECOM, PPWS) (OTHER)	0.50 0.25	36 MONTHS	0/0	48/24	31/15.5	47/23.5	63/31.5	9/4.5	0/0	78/36	6/3	12/6
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	0/0	12/3	0/0	0/0	0/0	60/15	36/9	0/0	36/9	36/9
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	6/3	1.6/8	1/5	1/5	1/5	1/5	1/5	1/5	1/5	1/5
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	1/3	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	2/1.5	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	3/1.5	6/3	0/0	0/0	0/0	0/0	10/5	0/0	0/0	20/10
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	5/2.5	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)	0.75 0.25	12 MONTHS (12 MONTHS) (6 MONTHS)	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
TOTAL NUCLEAR PLANT EXPERIENCE:			21.5	46	25.3	33.8	41.8	32	27	45.3	25	33.8

*SRO Upgrade Program to
train as an STA

HOT PARTICIPATION EXPERIENCE

TIME > 20% PHR/PHR (WKS)

STARTUP & SHUTDOWN (YES/NO)

MONTHS ON SHIFT

CHECK ONE OF THE FOLLOWING:

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)

AND SHIFT TECHNICAL ADVISORS (STA).

☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.☐ b. Shift advisors will probably be required, at least for some shifts.☒ c. Do not plan to use shift advisors unless some information is available.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

JOB TITLE: Supervising Operators
(NOT: 2)NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0						
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0						
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0						
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0						
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PPWS) (OTHER)	0.50 0.25	36 MONTHS	26/13 70/12	72/36 0/0	2/1 46/11.5	8/4 36/9						
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1/5 0/0	1/5 0/0	1/5 0/0	1/5 0/0						
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 0/0	0/0 7/3.5	0/0 0/0	0/0 10/5						
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.70	9 MONTHS	0/0	0/0	0/0	0/0						
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	0/0	0/0	0/0						
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	17/4.3	12/3	18/4.5	18/4.5						
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0						
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	0	2	1	2						
TOTAL NUCLEAR PLANT EXPERIENCE:			34.3	49.5	23	29.5						
HOT PARTICIPATION EXPERIENCE												
TIME > 20% PWR/DWR (WKS)												
STARTUP & SHUTDOWN (YES/NO)												
MONTHS ON SHIFT												

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"

CHECK ONE OF THE FOLLOWING:

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors unless some shift

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

OPERATING SHIFT EXPERIENCE

JOB TITLE: Shift Technical Advisors
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOCW, PPHS) (OTHER)	0.50 0.25	36 MONTHS	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0			
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.6/8 0/0	1.6/8 0/0	1/5 0/0	1/5 0/0	1/5 0/0	1/5 0/0	1/5 0/0			
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0			
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	5/2.5	5/2.5	0/0	0/0	0/0	0/0	0/0			
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	3/2.3	3/2.3	0/0	0/0	0/0	3/2.3	3/2.3			
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	50/12	47/11.8	84/12	21/5.3	20/5	17/4.3	35/8.8			
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	12	12	12	12	12	12	12			
TOTAL NUCLEAR PLANT EXPERIENCE:			36.8	36.6	29	22.3	22	23.6	28.1			
HOT PARTICIPATION EXPERIENCE												
TIME x 20% PWR/BWR (WKS)			0	0			0	0				
STARTUP & SHUTDOWN (YES/NO)			No	No			No	No				
MONTHS ON SHIFT			1	1			1	1				

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.

☐ c. Do not plan to use shift advisors and

DATE March 8, 1984PLANT NAME Perry Nuclear Power Plant
UTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Shift Supervisors
(NOTE 2)

ENTER DATA: MONTHS/ MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	36/36	0/0				
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0				
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	30/30	0/0	0/0	25/25	0/0				
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0				
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOOW, PPWS) (OTHER)	0.50 0.25	36 MONTHS	14/7 0/0	0/0 88/22	12/6 35/8.8	26/13 24/6	42/21 0/0	50/25 0/0				
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	.6/3 1/3	.6/3 .2/.6	.9/4.5 1/3	.9/4.5 1.2/3.6	.9/4.5 1/3	.6/3 1/3				
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	6/4.5 10/5	6/4.5 0/0	6/4.5 6/3	12.7/6.5 6/3	11/8.3 2/1	6/4.5 12/6				
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	7/3.5	7/3.5	9/4.5	9/4.5	9/4.5	7/3.5				
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	1.5/1.1	31/12	1.5/1.1	1.5/1.1	12/9	1.5/1.1				
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	64/12	76/12	82/12	80/12	18/4.5	77/12				
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0				
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	# * 9	 3	# 6	# * 10	* 1	 0				
TOTAL NUCLEAR PLANT EXPERIENCE:			48.1	92.6	53.4	67.2	115.3	58.1				
HOT PARTICIPATION EXPERIENCE												
TIME * 20% PWR/DWR (WKS)			6	130	6	6	262	2				
STARTUP & SHUTDOWN (YES/NO)			Yes	Yes	Yes	Yes	Yes	Yes				
MONTHS ON SHIFT			1.5	30	1.5	1.5	61	1.5				

* SRO Upgrade Program to train as an SIA
Associates Degree

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

CHECK ONE OF THE FOLLOWING:

NOTE 2: INCLUDE SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO) AND SRO'S, CRITICAL ADVISORS (STA).

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. The unit plan to use shift advisors.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OP. RATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Unit Supervisors
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, FWS) (OTHER)	0.50 0.25	36 MONTHS	94/36 24/0	18/9 36/9	0/0 0/0	2/1 46/11.5	74/36 0/0	0/0 0/0	0/0 0/0	36/18 30/7.5	0/0 0/0	
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.9/9.5 0/0	1.9/9.5 0/0	.9/4.5 1/3	1.9/9.5 0/0	1.5/7.5 0/0	.9/4.5 1/3	.9/4.5 1/3	1.9/9.5 0/0	.9/4.5 1/3	
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	11/8.3 12/6	12/9 8/4	0/0 0/0	10/7.5 3/1.5	6/4.5 10/5	12/9 3/1.5	11/8.3 12/6	12/9 6/3	10/7.5 0/0	
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	9/4.5 1.5/1.1	9/4.5 1.5/1.1	7/3.5 1.5/1.1	9/4.5 1.5/1.1	7/3.5 1.5/1.1	9/4.5 1.5/1.1	9/4.5 1.5/1.1	9/4.5 1.5/1.1	9/4.5 5/3.8	
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	35/8.8	24/6	33/8.3	28/7	42/10.5	50/12	44/11	37/9.3	77/12	
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	* #	*		*	*	*	*	*	*	
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	12	5	12	2	3	3	3	8	4	
TOTAL NUCLEAR PLANT EXPERIENCE:			86.6	55.4	32.4	45.6	71.1	38.6	41.4	67.1	39.3	
HOT PARTICIPATION EXPERIENCE												
TIME > 20% PWR/DWR (WKS)			6	6	6	6	6	6	6	6	8	
STARTUP & SHUTDOWN (YES/NO)			No	Yes	No	No	Yes	No	No	Yes	No	
MONTHS ON SHIFT			1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	5	

*SRO Upgrade Program to
train as an STA
Associates Degree

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO) AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors to satisfy the requirements of the utility plan.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Supervising Operators

(NOTE 2)

NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOCW, PPWS) (OTHER)	0.50 0.25	36 MONTHS	0/0 52/13	12/9 35/8.8	0/0 96/24	2/1 44/11	0/0 0/0	0/0 84/21	49/24 0/0	2/1 48/12	0/0 46/11.5	25/12.5 0/0
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.6/8 0/0	1.9/ 0/0	1.9/ 0/0	1.9/ 0/0	.9/4.5 1/3	1.9/9.5 0/0	1.6/8 0/0	1.9/9.5 0/0	1.9/9.5 0/0	1.9/9.5 0/0
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	6/4.5 0/0	14/ 3/1.5	14/ 10/5	14/ 10/5	6/4.5 2/1	14/10.5 11/5.5	6/4.5 2/1	13/3.8 3/1.5	6/4.5 0/0	8/6 2/1
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	7/3.5	9/4.5	9/4.5	9/4.5	9/4.5	9/4.5	7/3.5	9/4.5	9/4.5	9/4.5
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	33/8.3	8/2	23/5.8	19/4.8	55/12	21/5.3	25/6.3	19/4.8	60/12	23/5.8
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	2/5	0/0	3/8
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	1	0	0	0	5	1	5	1	0	4
TOTAL NUCLEAR PLANT EXPERIENCE:			38.3	45.8	59.3	46.3	34.5	57.3	52.3	44.6	42	44.1
HOT PARTICIPATION EXPERIENCE												
TIME x 20% PWR/BWR (WKS)												
STARTUP & SHUTDOWN (YES/NO)												
MONTHS ON SHIFT												

*SRO Upgrade Program to
train as an STANOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"

CHECK ONE OF THE FOLLOWING:

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

- ☐ a. Shift advisors must be used to satisfy the "hot participation
experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.

11
STANDARD FORM NO. 100-10

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

OPERATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Supervising Operators
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PPWS) (OTHER)	0.50 0.25	36 MONTHS	0/0 0/0	48/24 12/3	31/15.5 0/0	47/23.5 0/0	63/31.5 0/0	9/4.5 60/15	0/0 36/9	78/36 0/0	6/3 36/9	12/6 36/9
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 2.00	12 MONTHS (12 MONTHS) (9 MONTHS)	9/4.5 1/3	1.9/9.5 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	6/4.5 3/1.5	14/10.5 6/3	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 10/5	0/0 0/0	0/0 0/0	0/0 20/10
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	9/4.5 0/0	9/4.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0	7/3.5 0/0
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	60/12	16/4	27/6.8	25/6.3	25/6.3	26/6.5	28/7	25/6.3	28/7	23/5.8
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0	0/0
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	*									
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	2	0	0	1	1	3	3	0	3	0
TOTAL NUCLEAR PLANT EXPERIENCE:			32	58.5	33.8	42.3	50.3	40.5	35.5	53.8	33.5	42.3
HOT PARTICIPATION EXPERIENCE												
TIME * 20% PWR/DWR (WKS)												
STARTUP & SHUTDOWN (YES/NO)												
MONTHS ON SHIFT												

*SRO Upgrade Program to
train as an STANOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR
OPERATING SHIFT POSITIONS (OL APPLICANTS)"NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO)
AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors unless some information is...

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Supervising Operators
(NOTE 2)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0						
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0						
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0						
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0						
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOW, PPNS) (OTHER)	0.50 0.25	36 MONTHS	26/13 70/12	72/36 0/0	2/1 46/11.5	8/4 36/9						
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0						
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 0/0	0/0 7/3.5	0/0 0/0	0/0 10/5						
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	7/3.5	7/3.5	7/3.5	7/3.5						
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	0/0	0/0	0/0	0/0						
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	25/6.3	20/5	26/6.5	26/6.5						
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0						
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	0	2	1	2						
TOTAL NUCLEAR PLANT EXPERIENCE:			42.8	58	31.5	38						
HOT PARTICIPATION EXPERIENCE												
TIME > 20% PWR/BWR (WKS)												
STARTUP & SHUTDOWN (YES/NO)												
MONTHS ON SHIFT												

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO) AND SHIFT TECHNICAL ADVISORS (STA).

CHECK ONE OF THE FOLLOWING:

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors unless some unforeseen situation occurs.

DATE March 8, 1984PLANT NAME Perry Nuclear Power PlantUTILITY Cleveland Electric Illuminating CompanyO.L. DATE June, 1985

OPERATING SHIFT EXPERIENCE

(Projected at Fuel Load)

JOB TITLE: Shift Technical Advisors
(NOTE 2)NUCLEAR POWER PLANT EXPERIENCE
FOR OPERATING SHIFT POSITIONS (NOTE 1)

ENTER DATA: MONTHS/MONTHS X WEIGHTING FACTOR

TYPE OF EXPERIENCE	WEIGHTING FACTOR	MAXIMUM CREDIT	1	2	3	4	5	6	7	8	9	10
1. SAME TYPE COMMERCIAL SRO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
2. OTHER COMMERCIAL SRO	.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
3. SAME TYPE COMMERCIAL RO	1.00	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
4. OTHER COMMERCIAL RO	0.75	NO LIMIT	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
5. NAVY (MILITARY) NUCLEAR (RO, EWS, EOOM, PPWS) (OTHER)	0.50 0.25	36 MONTHS	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0			
6. SIMULATOR (REFERENCE PLANT) (SIMILAR)	5.00 3.00	12 MONTHS (12 MONTHS) (9 MONTHS)	1.9/9.5 0/0	1.9/9.5 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0	1.6/8 0/0			
7. NUCLEAR PLANT EXPERIENCE ON SHIFT (OWN PLANT) (LESS THAN 1 1/2 YEARS PRIOR TO F.L.) (MORE THAN 1 1/2 YEARS PRIOR TO F.L.)	0.75 0.50	24 MONTHS (12 MONTHS) (12 MONTHS)	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0	0/0 0/0			
8. LICENSED CLASSROOM TRAINING AND EXAM (OWN PLANT)	0.50	9 MONTHS	5/2.5	5/2.5	5/2.5	0/0	0/0	5/2.5	5/2.5			
9. PARTICIPATION AT OPERATING PLANT	0.75	12 MONTHS	12/9	12/9	0/0	0/0	0/0	12/9	12/9			
10. OTHER NUCLEAR PLANT EXPERIENCE	0.25	12 MONTHS	57/12	54/12	94/12	36/9	35/8.8	18/4.5	36/9			
11. CONDUCTING LICENSE TRAINING	0.25	9 MONTHS	0/0	0/0	0/0	0/0	0/0	0/0	0/0			
12. DEGREE (ENGINEERING, APPLIED SCIENCE OR EQUIVALENT) (BACHELORS DEGREE) (ASSOCIATES DEGREE)		12 MONTHS (12 MONTHS) (6 MONTHS)	12	12	12	12	12	12	12			
TOTAL NUCLEAR PLANT EXPERIENCE:			45	45	34.5	29	28.8	36	40.5			
HOT PARTICIPATION EXPERIENCE												
TIME * 20% PWR/BWR (WKS)			12	12				12	12			
STARTUP & SHUTDOWN (YES/NO)			Yes	Yes				Yes	Yes			
MONTHS ON SHIFT			6	6				6	6			

NOTE 1: SEE "INSTRUCTIONS FOR USE OF NUCLEAR POWER PLANT EXPERIENCE FACTORS FOR OPERATING SHIFT POSITIONS (OL APPLICANTS)"

CHECK ONE OF THE FOLLOWING:

NOTE 2: INCLUDE ALL SHIFT SUPERVISORS (SS), SHIFT SRO'S, REACTOR OPERATORS (RO) AND SHIFT TECHNICAL ADVISORS (STA).

- ☐ a. Shift advisors must be used to satisfy the "hot participation experience" requirements of the utility plan.
- ☐ b. Shift advisors will probably be required, at least for some shifts.
- ☒ c. Do not plan to use shift advisors unless some unforeseen event occurs.