

Commonwealth Edison Company  
LaSalle Generating Station  
2601 North 21st Road  
Marseilles, IL 61341-9757  
Tel 815-357-6761



March 23, 1995

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

This special report is submitted in accordance with LaSalle Unit 2 Operating License NPF-18, Appendix A, and Technical Specification Sections 3.7.6 and 6.6.c.

Technical Specification 3.7.6 requires that all fire rated assemblies and all sealing devices in fire rated assemblies (fire doors, fire windows, fire dampers, cable and piping penetration seals and ventilation seals) separating portions of redundant systems important to safe shutdown within a fire area shall be operable at all times.

On February 27, 1995, at 0830 hours, Fire Door 615 was inoperable for a period greater than seven days. The door was opened to support Unit 2 Refueling Outage maintenance and surveillance activities performed on Feedwater and Reactor Recirculation System Panels 2H13-P612 and 2H13-P634.

Fire Door 615 is located in the wall which separates Fire Subzones 4E2-1 and 4E2-2 in the Unit 2 Auxiliary Building on elevation 731'. Door 615 was opened to allow access to panels 2H13-P612 and 2H13-P634. When work is not being performed on the panels, Door 615 is closed.

An Hourly Fire Watch was established in accordance with the Action Statement of Technical Specification 3.7.6 and will remain in effect until all work is complete on panels 2H13-P612 and 2H13-P634. Work on these panels is not expected to be completed until the end of the current refueling outage (late April, 1995).

A Special Report is required because the door was not restored to an operable status within seven days. Door 615 will not be considered operable until all work is completed on the panels, the Hourly Fire Watch is terminated, and the Fire Impairment is permanently cleared.

Sincerely,

D. J. Ray  
Station Manager  
LaSalle County Station

DJR/RV/lja

cc: NRC Region III Administrator  
NRC Senior Resident Inspector  
INPO - Records Center  
IDNS Resident Inspector  
Nuclear Licensing Administrator

040087

A Unicom Company

9504040193 950329  
PDR ADOCK 05000374  
S PDR

JE221/0