



ENTERGY

Entergy Operations, Inc.
1448 S.R. 333
Russellville, AR 72801
Tel 501 858-5000

August 18, 1995

2CAN089502

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, DC 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report 50-368/95-001-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i)(B), 10CFR50.73(a)(2)(ii)(B), and 10CFR50.73(a)(2)(v), enclosed is the subject report concerning the unanticipated effect of an analyzed failure of a DC electrical bus upon the train of the Emergency Feedwater system containing the AC motor-driven pump.

Very truly yours,

Dwight C. Mims
Director, Licensing

DCM/tfs

enclosure

220073

9508230088 950818
PDR ADDCK 05000368
S PDR

JE22

U. S. NRC
August 18, 1995
2CAN089502 Page 2

cc: Mr. Leonard J. Callan
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, GA 30339-5957