




Wisconsin Electric POWER COMPANY
231 WEST MICHIGAN, MILWAUKEE, WISCONSIN 53201



August 8, 1975

Mr. Benard C. Rusche, Director
Office of Nuclear Reactor Regulation
U. S. NUCLEAR REGULATORY COMMISSION
Washington, D. C. 20555

Dear Mr. Rusche:

CORRECTION TO
LICENSEE EVENT REPORT NO. 50-266/75-4A
"B" STEAM GENERATOR TUBE FAILURE
POINT BEACH NUCLEAR PLANT

In our letter to you of June 26, 1975, we submitted the recovery report concerning details of the repair and our intended corrective action following a steam generator tube failure at Point Beach Nuclear Plant on February 26, 1975. In reviewing the details of data provided in that letter, we noted an error in volumetric determination of air particulate filter activity. We should appreciate your noting the following correction:

1. Page 13, Table 5, Air Particulate Filters,
West Boundary, vol (m³) = 120, Gross Beta =
0.09 ± 0.02 pCi/m³.

Very truly yours,

Executive Vice President

Sol Burstein

COPY SENT REGION

8403260300 750808
PDR ADDCK 05000266
S PDR

50-266
inquiry

8676