




**LOUISIANA  
POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 15, 1984



W3K84-0615  
Q-3-A35.07.80

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-0093 dated January 16, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 80  
"Unsatisfactory Stroking of EFW Pump Turbine Steam Shut Off Valves"  
Fourth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on March 9, 1984.

At the present time corrective action is completed. However, further testing is required during Post Core Hot Functional Testing (HFT).

An Updated or Final Report will be submitted to the USNRC on July 13, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8403270046 840315  
PDR ADOCK 05000382  
S PDR

IE-27  
40

Mr. John T. Collins  
March 15, 1984  
W3K84-0615  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130