

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

34 MAR 26 AIO: 79 March 21, 1984

BLRD-50-438/84-21
BLRD-50-439/84-20

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - INCORRECT INSULATION WEIGHTS FOR
INTAKE PUMPING STATION PIPING - BLRD-50-438/84-21, BLRD-50-439/84-20 -
SUPPLEMENTAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Ross Butcher on February 21, 1984 in accordance with 10 CFR 50.55(e) as NCR
BLN BLP 8405. In our first interim report dated March 14, 1984, we had
inadvertently omitted the fact that our next report would be submitted on
November 30, 1984.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills

L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8403300021 840321
PDR ADOCK 05000438
S PDR

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

OFFICIAL COPY

5427

1/0