



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

March 26, 1984

RBG- 17,418

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Final Report/DR-89

Gulf States Utilities Company has completed its investigation of DR-89 concerning the RTE primary knife-type disconnect used on the Standby Diesel Generator and has determined that this condition is not reportable under 10CFR50.55(e).

Sincerely,

for J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

JEB/PJD/je

cc: Director of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

NRC Resident Inspector - Site

8404030527 840326  
PDR ADOCK 05000458  
S PDR

IE-27

1/0