



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

March 26, 1984

RBG- 17,419

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-118

Gulf States Utilities Company has not completed its investigation of DR-118 concerning the penetration of welds for platform channels on the Primary Shield Wall. An interim or final status report will be provided by April 24, 1984.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JE
JEB/PJD/je

cc: Director of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

NRC Resident Inspector - Site

8404030537 840326
PDR ADOCK 05000458
S PDR

IE-27 1/0