

DmB

U- 0703
0982-L
L08(IEB83-08)-84(03-22)-L

ILLINOIS POWER COMPANY



CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

March 22, 1984

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Clinton Power Station Unit 1
IE Bulletin No. 83-08

Dear Mr. Keppler:

This is in response to the subject IE Bulletin No. 83-08 on the matter of reactor trip breaker failures. Westinghouse DB, Westinghouse DS, General Electric AK-2 or similar breakers with undervoltage trip attachments (UVTA) are not used in safety related applications at the Clinton Power Station.

I hereby affirm that the information in this letter is correct to the best of my knowledge.

Sincerely yours,

A handwritten signature in cursive script, appearing to read 'B. P. Hall'.

B. P. Hall
Vice President

GEW:lam

cc: G. A. Harrison, NRC Clinton Licensing Project Manager
NRC Resident Office
Illinois Department of Nuclear Safety
Director - Office of I&E USNRC, Washington, DC 20555

B404090199 B40322
PDR ADOCK 05000461
Q PDR

MAR 28 1984

IE// 1/0