



DmB



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500


March 21, 1984

Mr James G Keppler, Director
Region III, Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glenn Ellyn, Illinois 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Response to IE Bulletin 83-08

A review of records and a physical inspection of equipment has shown that there are no breakers of the type identified in the bulletin, and no other types of breakers that use an undervoltage trip feature that are used in safety related applications at Monticello. There are currently no plans to install such devices. We believe that this addresses your concerns, however, if more information is needed, please contact our offices.


C E Larson
Director, Nuclear Generation

CEL/bd

c: Document Control Desk, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
G Charnoff

8404090321 840321
PDR ADOCK 05000263
Q PDR

MAR 26 1984

IE//11

(I.E. BULLETIN FORMAT)

UNITED STATES NUCLEAR REGULATORY COMMISSION

NORTHERN STATES POWER COMPANY

MONTICELLO NUCLEAR GENERATING PLANT

Docket No. 50-263

RESPONSE TO I.E. BULLETIN NO. 83-08

Northern States Power Company, a Minnesota corporation, hereby submits the response to I.E. Bulletin No. 83-08 for the Monticello Nuclear Generating Plant.

This letter contains no restricted or other defense information.

NORTHERN STATES POWER COMPANY

By: C. E. Larson
C. E. Larson
Director, Nuclear Generation

On this 21st day of March, 1984, before me a notary public in and for said County, personally appeared C. E. Larson, Director, Nuclear Generation, and being first duly sworn acknowledged that he is authorized to execute this document on behalf of Northern States Power Company, that he knows the contents thereof and that to the best of his knowledge, information and belief, the statements made in it are true and that it is not interposed for delay.

Betty J. Dean

