



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
April 5, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0939

NRC Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
LICENSEE EVENT REPORT 2-84-5

Gentlemen:

On March 8, 1984, it was discovered that technical specifications required actions concerning performance of maintenance on Reactor Water Cleanup System primary containment isolation valve 2-G31-F004 were not met. LER 2-84-5 was to have been submitted to your office by April 6, 1984. However, investigation and evaluation of this event is not yet complete. It is anticipated that this report will be submitted by May 7, 1984.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/sdl/LETPS1

Enclosure

cc: Mr. J. P. O'Reilly

8404100247 840405
PDR ADOCK 05000324
S PDR

IE22
10