




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 29, 1984

W3K84-0741  
Q-3-A35.07.37

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: LP&L Letter W3K84-0153 dated January 24, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 37  
"Temperature Detectors (RTD's) Failures"  
Tenth Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on March 30, 1984.

Closure of the subject SCD is dependent upon successful completion of response time testing of the hot and cold leg RTD's.

An update or final report will be submitted to the USNRC on July 13, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8404100358 840329  
PDR ADOCK 05000382  
S PDR

IE-27 10

Mr. John T. Collins  
March 29, 1984  
W3K84-0741  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814