



UNIVERSITY OF MISSOURI-ROLLA

May 11, 1984

Nuclear Reactor Facility

Nuclear Reactor  
Rolla, Missouri 65401  
Telephone: (314) 341-4236

Mr. C.E. Norelius, Director  
Division of Resident and Projects Inspection  
U.S. Nuclear Regulatory Commission, Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Norelius:

This letter is to inform you that the staff at the UMR Reactor Facility and the campus Health Physicist, Ray Bono, have reviewed the 600-series of the Standard Operating Procedures, which have to do with radiation protection matters. We have re-written several of them (see the enclosed) and they have been put into effect as of this week.

There are a couple of the SOP's, 601, Decontamination Procedures 602, Handling Injured in Radiation Accidents, which did not need a revision. Their technical content is adequate; however, their format could be improved and they will be changed to our new format later.

We hope that you will find these recently-revised SOP's to be satisfactory.

Sincerely,

A handwritten signature in cursive script that reads 'Albert E. Bolon'.

Albert E. Bolon  
Director

cc. Dean Warner  
John Vaughn  
Nord Gale  
N. Tsoulfanidis

8405220413 840517  
PDR ADOCK 05000123  
Q PDR

MAY 14 1984