

May 18, 1984  
SBN- 658  
T.F. Q2.2.2

United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Attention: Mr. Richard W. Starostecki, Director  
Division of Project and Resident Programs

References: (a) Construction Permits CPPR-135 and CPPR-136, Docket  
Nos. 50-443 and 50-444  
(b) Telecon of April 19, 1984, A. L. Legendre (YAEC) to  
R. W. Borchardt (NRC Region I)

Subject: Interim 10CFR50.55(e) Report; Fisher Controls Valve Operator  
Bracket Welds

Dear Sir:

On April 19, 1984, we reported a potential 10CFR50.55(e) deficiency to  
Region I [Reference (b)] regarding weld deficiencies on Fisher Controls  
Company valve operator brackets.

It has been determined that this item is reportable under 10CFR50.55(e).  
The following information is being filed pursuant to the interim reporting  
provision of 10CFR50.55(e)(3).

A. Description of Deficiency

Numerous weld deficiencies were discovered on valve operator  
brackets for service water system valves (ASME III & ANSI B31.1)  
manufactured by Fisher Controls Company. The welds do not comply  
with the specification requirements of the American Welding Society  
(AWS) standards in regard to undercut, size, voids, fusion, and  
corner fill.

The brackets are mounted on butterfly valves for the service water  
system only. To date, seventy-two brackets have been determined to  
have weld deficiencies.

B. Analysis of Safety Implication

Failure of the bracket welds could affect the operability of the  
valves.

8405300105 840518  
PDR ADOCK 05000443  
S PDR


C. Corrective Action Taken

1. All Fisher Controls valve operator brackets are being inspected for weld deficiencies. Those brackets having weld deficiencies will be returned to Fisher Controls for repair. Repaired brackets will be inspected upon receipt.
2. United Engineers has instructed Fisher Controls on February 24, 1984 to reinstruct personnel on welding acceptance criteria.
3. A review of purchasing documents will be performed to identify any other Fisher Control product used on the Seabrook Project.

We estimate that all affected valve brackets will be repaired by June 1, 1984. Region 1 will be notified upon verification of completion of the corrective action.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY



John DeVincentis  
Engineering Manager

cc: Atomic Safety and Licensing Board Service List

Director, Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

William S. Jordan, III, Esquire  
Harmon & Weiss  
1725 I Street, N.W. Suite 506  
Washington, DC 20006

Roy P. Lessy, Jr., Esquire  
Office of the Executive Legal Director  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Robert A. Backus, Esquire  
116 Lowell Street  
P.O. Box 516  
Manchester, NH 03105

Philip Ahrens, Esquire  
Assistant Attorney General  
Department of the Attorney General  
Augusta, ME 04333

Mr. John B. Tanzer  
Designated Representative of  
the Town of Hampton  
5 Morningside Drive  
Hampton, NH 03842

Roberta C. Pevear  
Designated Representative of  
the Town of Hampton Falls  
Drinkwater Road  
Hampton Falls, NH 03844

Mrs. Sandra Gavutis  
Designated Representative of  
the Town of Kensington  
RFD 1  
East Kingston, NH 03827

Jo Ann Shotwell, Esquire  
Assistant Attorney General  
Environmental Protection Bureau  
Department of the Attorney General  
One Ashburton Place, 19th Floor  
Boston, MA 02108

Senator Gordon J. Humphrey  
U.S. Senate  
Washington, DC 20510  
(Attn: Tom Burack)

Diana P. Randall  
70 Collins Street  
SEabrook, NH 03874

Donald E. Chick  
Town Manager  
Town of Exeter  
10 Front Street  
Exeter, NH 03833

Brentwood Board of Selectmen  
RED Dalton Road  
Brentwood, New Hampshire 03833

Edward F. Meany  
Designated Representative of  
the Town of Rye  
155 Washington Road  
Rye, NH 03870

Calvin A. Canney  
City Manager  
City Hall  
126 Daniel Street  
Portsmouth, NH 03801

Dana Bisbee, Esquire  
Assistant Attorney General  
Office of the Attorney General  
208 State House Annex  
Concord, NH 03301

Anne Verge, Chairperson  
Board of Selectmen  
Town Hall  
South Hampton, NH 03842

Patrick J. McKeon  
Selectmen's Office  
10 Central Road  
Rye, NH 03870

Carole F. Kagan, Esq.  
Atomic Safety and Licensing Board Panel  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Angie Machiros  
Chairman of the Board of Selectmen  
Town of Newbury  
Newbury, MA 01950

Town Manager's Office  
Town Hall - Friend Street  
Amesbury, Ma. 01913

Senator Gordon J. Humphrey  
1 Pillsbury Street  
Concord, NH 03301  
(Attn: Herb Boynton)

Richard E. Sullivan, Mayor  
City Hall  
Newburyport, MA 01950

NOV 11 1981  
RECEIVED