



Commonwealth Edison
Byron Nuclear Station
4450 North German Church Road
Byron, Illinois 61010

April 3, 1992

LTR: BYRON 92-0215
FILE: 2.7.300

Mr. A. Bert Davis
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: Annual Environmental Operating Report for Facility
Licenses NPF-37 and 66

Dear Mr. Davis:

Attached you will find the Annual Environmental Operating Report as required by the Operating License, Appendix B, Section 5.4 for Facility Licenses NPF-37 and 66. The period of the report is from January 1, 1991 to December 31, 1991.

The report was reviewed against the objectives of the Environmental Protection Plan as stated in Section 1.0 Appendix B to the Operating License, and it has been determined that these objectives are being met.

A summary and analysis of the results of environmental protection activities required by Appendix B, Section 4.2 are provided in Attachment A.

There were no non-compliances to the Environmental Protection Plan; therefore, no corrective actions were required by Appendix B, Section 5.4.1(1). There were no changes in Station design, operation, or tests and experiments which involved a potentially significant unreviewed environmental question as defined in Section 3.1. There were no non-routine reports submitted per Section 5.4.2.

050104

(3596z/VS)

9204130004 920403
PDR ADCK 05000454
R PDR


IE47
11

BYRON 92-0215

Page 2

In accordance with Regulatory Guide 10.1, one copy of this report is provided for your use and 18 copies are being submitted directly to the Document Control Desk, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555.

Sincerely,



R. Pleniewicz
Station Manager
Byron Nuclear Power Station

SP/LAL/ph

Attachment

cc: NRC Resident Inspector
Document Control Desk (18 copies)
Site Nuclear Licensing Administrator
Environmental Services