

RECEIVED
MAY 25 1984
ARIZONA PUBLIC SERVICE COMPANY

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

MAY 25 1984
ANPP-29603-TDS/TRB

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-11
A 50.55(e) Potentially Reportable Deficiency Relating To
Conduit Used In PVMP Instrumentation Is Contaminated.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Johnson and T. Bradish
on March 8, 1984.
(B) ANPP-29213, dated April 3, 1984 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
May 29, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by August 31, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB:db

cc: See Page Two

Mr. T. W. Bishop
DER 84-11
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
L. A. Souza
D. E. Fowler
J. Vorees
J. R. Bynum
J. M. Allen
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339