

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

January 24, 1983

Office of Environmental Programs
Waste Management Administration
201 West Preston Street
Baltimore, Maryland 21201

Attention: Mr. Ronald Parise

Re: Maryland State Discharge
Permit No. 74-DP-0187 and
NPDES Permit No. MD 0002399

Dear Mr. Parise:

On January 12, 1983, outfall 001, monitoring point 101 experienced a total residual chlorine of about 3.0 ppm which is greater than the specification of 0.5 ppm. This condition existed for about 4 hours due to failure of a pump used to add the dechlorinating agent. Spare pumps are kept on site and allowed rapid corrective action once the problem was identified.

This matter had been communicated to you by telephone on January 13, 1983. Please feel free to call if you have any further questions.

Very truly yours,

LBR

L. B. Russell
Plant Superintendent

LBR/EME/fcb

9201270291 920116
PDR ADCK 05000317
S PDR