

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

February 25, 1982

Division of Sewerage
Inspection and Compliance Program
Office of Environmental Programs,
Room 2A4
201 West Preston Street
Baltimore, Maryland 21201

Attention: Mr. Ronald Parise


Re: Maryland State Discharge
Permit No. 74-FP-0187A and
NPDES Permit No. MD 0002399

Dear Mr. Parise:

At 1000 hours on February 19, 1982, the coliform results from the Wednesday, February 17, 1982, sample were analyzed and found to be 160 mpn/100 ml, above the compliance limit of 70 mpn/100 ml. This condition existed until 1515 hours on Monday, February 22, 1982, when the coliform was found to be 44 mpn/100 ml. A report of this incident was verbally transmitted to your office on February 19, 1982.

The noncompliance resulted from a contaminated sodium thiosulfate chemical addition tank. This condition has been corrected.

Very truly yours,



L. B. Russell
Plant Superintendent

LBR/RES/fcb