



84 JUN 5 P12:22

Carolina Power & Light Company

P. O. Box 165, New Hill, North Carolina 27562
May 23, 1984

FILE: SH N-2/18
Item 171

MQAH 84-226

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400
MISLOCATED REBAR IN MASONRY BLOCK WALLS

Dear Mr. O'Reilly:

This is to confirm the May 23, 1984 telephone conversation between Mr. K. V. Hate' (CP&L) and Mr. A. Hardin (NRC). Mr. Hardin was informed that the April 27, 1984 potentially reportable item, pertaining to the location of the rebar in the block walls not being as specified by the design requirements, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e).

Thank you for your consideration in this matter.

NJC/mt

Yours very truly,

cc: Mr. R. C. DeYoung
Mr. G. Maxwell
Mr. R. L. Prevatte

N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

8406110313 840523
PDR ADOCK C5000400
S PDR

OFFICIAL COPY

1E27 d