



**LOUISIANA  
POWER & LIGHT**

142 DELARONDE STREET  
NEW ORLEANS, LOUISIANA

P.O. BOX 8008  
70174-8008

(504) 386-2345

September 18, 1984

W3P84-2581  
Q-3-A35.07.61  
3-A1.01.04

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: 1) LP&L letter W3K84-2054 dated August 31, 1984.  
2) NRR letter dated June 13, 1984 from Darrell G. Eisenhut to J.M. Cain

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Reopening of Significant Construction Deficiency No. 61  
"Linear Crack in Stainless Steel Tubing"

Because of ongoing efforts associated with resolution of issues in reference 2, it may be necessary to modify reference 1. We therefore have elected to reopen SCD61 pending completion of those efforts. A final report will be issued upon completion of this effort which is currently scheduled for October 5, 1984.

Very truly yours,

K.W. Cook  
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8410100422 840918  
PDR ADOCK 05000382  
S PDR

IE-27  
1/0

Mr. John T. Collins  
W3P84-2581  
Page 2

cc: Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M. Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814