



JUL 18 1995

L-95-208
10 CFR §50.36

Stewart D. Ebnetter
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta St., N.W., Suite 2900
Atlanta, Ga. 30323

Mr. Ebnetter:


Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
Standby Steam Generator Feedwater Pump B
Returned to Service

On April 21, 1995, we submitted a Special Report to you under letter L-95-089, in accordance with Technical Specifications 3.7.1.6 and 6.9.2. The purpose of the Special Report was to notify you that the B Standby Steam Generator Feedwater (SSGF) Pump was expected to be removed from service on May 17, 1995, and expected to be returned to service on July 10, 1995. In the Special Report we committed to send you a followup letter confirming that the pump has been returned to service.

This letter is to confirm that the B SSGF Pump has been returned to service. Following post-modification testing, the pump was released to Operations Department, who successfully completed the normal monthly surveillance test on the pump on July 13, 1995. Additionally, Amendments 164/158 to the Turkey Point Technical Specifications will be implemented by August 12, 1995.

Should there be any questions on this information please contact us.

Very truly yours,


T. F. Plunkett
Vice President
Turkey Point Plant

CLM 9510180386 950718
PDR ADOCK 05000250
P PDR

cc: USNRC, Document Control Desk, Washington, D.C.
T. P. Johnson, Senior Resident Inspector, USNRC, Turkey
Point Plant

180001



an FPL Group company

J.P. BRANNIN
J. PERKINS
D. BAKER

S. BILGER
W. NAZARKEWICH
J. DeBLASIO

INPO
C.F. FERRIDAY
L.D. LEON

O. PRESTON
M.A. SCHOPPMAN
R.P. CROTEAU

11005 10