

11
2237
GPO 917-926



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

September 25, 1984

DJS Ltr #84-959

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Update to Reportable Occurrence Report #83-29/03X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation. This update clarifies cause of event and corrective action.

D.J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/jkl

Enclosure

cc: J.G. Keppler, Regional Administrator, Region III
File/Numerical
File/NRC

IE22
1/1

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT	YEAR	NO.
D - 12	-	3	- 83	- 56

PART 1	TITLE OF EVENT	OCCURRED	
	Containment Sprays Interlock	7/26/83	1100
	REASON FOR SUPPLEMENTAL REPORT	DATE	TIME
	Clarify cause of event and corrective actions.		
PART 2			
ACCEPTANCE BY STATION REVIEW	<u>J. Brunner</u>	<u>J.A. Ciola</u>	
DATE	<u>9/26/84</u>	<u>10/8/84</u>	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Hirt</u>	<u>10/10/84</u>	
	STATION SUPERINTENDENT	DATE	

IE 22
145