

RECEIVED
NRC

Arizona Public Service Company

1984 JUL 23 PM 2:20

July 18, 1984
ANPP-29988-TDS/TRB REGIONAL

U. S. Nuclear Regulatory Commission
Region V
Creskside Oaks Office Park
1440 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Deficiency Evaluation Report 84-43
A 50.55(e) Evaluation Relating To HPSI 3" Gate Valve Failure
To Open.
File: 84-019-026; D.4.33.2


Reference: Telephone Conversation between P. Narbut and T. Bradish on
June 22, 1984

Dear Sir:

The NRC was notified of the subject Deficiency Evaluation in the
referenced telephone conversation, with a determination of reportability
to be made within thirty (30) days (July 22, 1984).

The deficiency has subsequently been determined to be Not Reportable
under the requirements of 10CFR50.55(e), therefore no written report is
required. Necessary documentation of the evaluation will be maintained
in APS files.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB:db

cc: See Page Two

8408010388 840718
PDR ADDCK 05000528
S PDR

1/0
IE-27

Mr. T. W. Bishop
DER 84-43
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
J. A. Brand
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
R. P. Zimmerman
S. R. Frost
J. Self
D. Canady
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339