

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2DOCKET NUMBER (2)  
0 5 0 0 0 3 6 1 1 OF 0 1TITLE (4)  
CONTAINMENT PURGE ISOLATION SYSTEM ACTUATION

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
06	25	84	84	035	000	07	25	84			0 5 0 0 0 0 0 0

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																					
POWER LEVEL (10) 0 1 0 1 0	5	20.402(b)	20.406(a)(1)(i)	20.406(a)(1)(ii)	20.406(a)(1)(iii)	20.406(a)(1)(iv)	20.406(a)(1)(v)	20.406(c)	50.38(c)(1)	50.38(c)(2)	50.73(a)(2)(i)	50.73(a)(2)(ii)	50.73(a)(2)(iii)	50.73(a)(2)(iv)	50.73(a)(2)(v)	50.73(a)(2)(vi)	50.73(a)(2)(vii)	50.73(a)(2)(viii)(A)	50.73(a)(2)(viii)(B)	50.73(a)(2)(ix)	73.71(b)	73.71(c)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)

LICENSEE CONTACT FOR THIS LER (12)  
NAME  
J. G. HAYNES, STATION MANAGER  
TELEPHONE NUMBER  
7 1 4 4 9 2 1 - 7 1 7 0 1 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM

SUPPLEMENTAL REPORT EXPECTED (14)  
YES (If yes, complete EXPECTED SUBMISSION DATE) NO  
EXPECTED SUBMISSION DATE (15)  
0 1 9 0 1 7 8 4

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On June 25, 1984, at 1318, with Unit 2 in Mode 5 and a main purge in progress, the Containment Area Radiation Monitor 2RE-7804 (EIIS Identifier RT) reached its alarm setpoint and initiated the Train 'A' Containment Purge Isolation System (CPIS) (EIIS Identifier VA) due to a brief increase in airborne activity following removal of the Steam Generator (EIIS Identifier SG) primary manway diaphragm for tube leak repair work. All CPIS actuated components functioned properly. At 1349, a new setpoint was installed based on a new release permit and containment normal purge was re-established.

Our investigation is continuing to assess this event under alternative conditions and to identify appropriate corrective actions. The results of our investigation will be reported in a revision to this LER by September 7, 1984.

8408060223 840725  
PDR ADOCK 05000305  
S PDR

*Southern California Edison Company*

**SCE**

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES  
STATION MANAGER

July 25, 1984

TELEPHONE  
(714) 492-7700

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket No. 50-361  
30-Day Report  
Licensee Event Report No. 84-035  
San Onofre Nuclear Generating Station, Unit 2

Pursuant to 10 CFR 50.73(a)(2)(iv), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the actuation of the Containment Purge Isolation System. Neither the health and safety of plant personnel nor the public were affected by this event.

If you require any additional information, please so advise.

Sincerely,

*JG Haynes*

Enclosure: LER No. 84-035

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)  
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, NRC Region V)

Institute of Nuclear Power Operations (INPO)

IE22  
1/1