



**Consumers
Power
Company**

James W Cook
Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnell Road, Jackson, MI 49201 • (517) 788-0453

July 11, 1984

PRINCIPAL STAFF			
✓ RA	✓ AD	DRP	✓ Wright 3
D/RA		DRS	
RC		DRSS	
PAO		ML	
SGA		OL	
EIC		OI	
DRMA		FILE	✓ 100

Mr J G Keppler, Administrator
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER

MIDLAND DOCKET NOS 50-329, 50-330

IE BULLETIN 83-07: APPARENTLY FRAUDULENT MATERIALS SUPPLIED BY RAY MILLER INC
FILE 0505.12 SERIAL 29826

REFERENCE: CP CO INTERIM IE BULLETIN 83-07 RESPONSE TO J G KEPPLER DATED
MARCH 22, 1984

In accordance with the directive given in IE Bulletin 83-07, this report identifies the activities that have been completed and/or are in progress, to resolve the issue of apparently fraudulent material supplied by Ray Miller, Inc.

An investigation has been performed by Bechtel San Francisco Central Supplier Quality (SFHO) Department to determine if any sub-suppliers have supplied Ray Miller material to the Midland Plant. The following is a summary of this investigation:

1. To date, of the 451 letters mailed from SFHO, 93 letters went to vendors that supplied material to the Midland Project. Bechtel Ann Arbor has received 93 (100%) of the Midland responses. The investigation of the sub-suppliers is now closed.
2. Of the 93 "response letters," only one supplier (Richmond Engineering (RECO)) has identified Ray Miller material being furnished to Midland. The identified materials are four flanges 4"-150RF50, SA182F 316 stainless steel. Identified material was furnished on Bechtel Power Corporation Purchase Order 722-M-65-AC. Subject purchase order was non-Q-listed for two resin storage tanks.

B&W has completed a review of their QA data packages and purchase order packages, which include the names of their suppliers, and have compared these suppliers with the lists of purchasing and receiving companies that were given in the Bulletin. The following is the result of that review:

1. Control and Instrumentation (C&I) related equipment

8408070183 840711
PDR ADCK 05000329
G PDR

oc0784-0888a100

AUG 1 1984

IE// 11

This category represents the safety-related pressure boundary components in the C&I Systems.

- a. There were approximately 34 QA data packages to review for this equipment.
- b. All of these QA packages have been reviewed.
- c. None of the Ray Miller customers listed in the Bulletins were identified as having supplied safety-related hardware to the Midland Plant.

2. Spare Parts for the Midland Plant

This category represents safety-related equipment that has either been purchased or is on order.

There were approximately 70 purchase order packages.

- b. All of these purchase order packages have been reviewed.
- c. None of the Ray Miller customers listed in the Bulletin were identified as having supplied safety-related hardware to the Midland Plant.

3. B&W Systems other than 1 and 2 above

- A. There were approximately 75 QA data packages reviewed for these systems.
- B. All of the QA data packages have been reviewed.
- C. This review has resulted in the following findings:
 - 1) Atlas Industries, a supplier for the letdown coolers, obtained flanges from the Gulf and Western, Taylor Forge division in Long Island City not the New Jersey location for Gulf and Western listed in Bulletin 83-07.
 - 2) Dresser Industries, a Midland Plant supplier, obtained some materials from Huntington Alloys in the 1977 time frame.

Additional inquiries are being made directly to these sub-suppliers.

The final report on IE Bulletin 83-07 is planned for September 1, 1984.

James W. Crook

JWC/WFK/fme

CC DSHood, NRR Project Manager, Washington

oc0784-0888a100

Midland Project Manager, Region III
Midland Project Section Chief, Region III
Midland Resident Inspector, Midland

CONSUMERS POWER COMPANY
Midland Units 1 and 2
Docket No 50-329, 50-330

Letter Serial 29826 Dated July 11, 1984

At the request of the Commission and pursuant to the Atomic Energy Act of 1954, and the Energy Reorganization Act of 1974, as amended and the Commission's Rules and Regulations thereuader, Consumers Power Company submits an interim response to IE Bulletin 83-07 regarding the apparently fraudulent material supplied by Ray Miller, Inc.

CONSUMERS POWER COMPANY

By

James W. Cook
James W Cook, Vice President
Projects, Engineering and Construction

Sworn and subscribed before me this 30 day of July, 1984.

Bartola B. Hammond
Notary Public
Jackson County, Michigan

My Commission Expires Sept 8, 1984