

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

October 31, 1995
ST-HL-AE-5223
File No.: G03.11
10CFR50.63

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project
Units 1 and 2
Docket Nos. STN 50-498; STN 50-499
Revised Position on 10CFR50.63
"Loss of All Alternating Current Power"

Reference: Letter from T. H. Cloninger to the Nuclear Regulatory Commission Document Control Desk dated March 1, 1995 (ST-HL-AE-5010)

This letter clarifies South Texas Project's position on NUMARC 87-00 Guidance 4.2.3.1(c) found on page 22 of 48 of Attachment 1 to the referenced correspondence. South Texas Project's position described that procedure OPOP04-ZO-0002 states the Shift Supervisors shall perform certain actions in preparation for the onset of a hurricane. Five actions are described in the referenced letter indicating these action steps are implemented when a "hurricane watch" for the Texas coast and the South Texas Project is issued. The referenced letter should state that the first three actions are implemented when a "hurricane watch" for the Texas coast and the South Texas Project site is issued. The last two actions are implemented when a "hurricane warning" for the Texas coast and the South Texas Project site is issued.

This clarification is not considered to have a significant impact on the revised South Texas Project Station Blackout submittal for the following reasons:

- (1) The NUMARC 87-00 Guidance contains no specific or implied criteria for the actions described in South Texas Project's preparation for the onset of a hurricane.

9511060017 951031
PDR ADOCK 05000498
P PDR

MISC-95/5223

Project Manager on Behalf of the Participants in the South Texas Project

Acc
1/0


(2) The Nuclear Regulatory Commission Safety Evaluation Report of July 24, 1995 contains no specific or implied discussions of South Texas Project's actions for preparation for the onset of a hurricane that affected conclusions of South Texas Project's revised position on 10CFR50.63.

In addition, page 26 of 48 of Attachment 1 to the referenced correspondence states STPEGS position for paragraph 4.2.3(b) of NUMARC 87-00 Guidance for actions for a tornado as follows:

"OPGP03-ZV-0001 provides requirements for restoration of tornado dampers to the open position, should they be actuated by an actual tornado strike."

The referenced procedure number should be "OPOP04-ZO-0002" instead of "OPGP03-ZV-0001".

If you should have any questions, please contact Mr. K. J. Taplett at (512) 972-8416 or me at (512) 972-8686.



L. E. Martin
General Manager,
Nuclear Assurance & Licensing

KJT/lf

Leonard J. Callan
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Thomas W. Alexion
Project Manager
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001 13H15

David P. Loveless
Sr. Resident Inspector
c/o U. S. Nuclear Regulatory Comm.
P. O. Box 910
Bay City, TX 77404-0910

J. R. Newman, Esquire
Morgan, Lewis & Bockius
1800 M Street, N.W.
Washington, DC 20036-5869

K. J. Fiedler/M. T. Hardt
City Public Service
P. O. Box 1771
San Antonio, TX 78296

J. C. Lanier/M. B. Lee
City of Austin
Electric Utility Department
721 Barton Springs Road
Austin, TX 78704

Central Power and Light Company
ATTN: G. E. Vaughn/C. A. Johnson
P. O. Box 289, Mail Code: N5012
Wadsworth, TX 77483

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61067
Houston, TX 77208

Institute of Nuclear Power
Operations - Records Center
700 Galleria Parkway
Atlanta, GA 30339-5957

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

Richard A. Ratliff
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

U. S. Nuclear Regulatory Comm.
Attn: Document Control Desk
Washington, D. C. 20555-0001

J. R. Egan, Esquire
Egan & Associates, P.C.
2300 N Street, N.W.
Washington, D.C. 20037

J. W. Beck
Little Harbor Consultants, Inc.
44 Nichols Road
Cohasset, MA 02025-1166