

Update Report:
Previous Report Date: 12-16-83

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

CON'T

REPORT
SOURCEREPORT
SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 Technical Specifications 3.1.3.7, 6.9.1.9b 90

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

7	8	9		(30)	METHOD OF	80
<hr/>						

ACTIVITY CONTENT

(36)

7 8 9 10 11 44 45 50

PERSONNEL EXPOSURES

7	8	9	11	12	13	80
			PERSONNEL INJURIES			

7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (42)

7 8 9 10
PUBLCITY
8408180075 840728
PDR ADPOCK 05000325
NRC USE ONLY

[illegible]

PHONE: 919-457-9521

CP&L

Carolina Power & Light Company

84 JUL 31 A 9: 09

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

July 27, 1984

FILE: B09-13510C
SERIAL: BSEP/84-1666


Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, N.W.
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SUPPLEMENT TO LICENSEE EVENT REPORT 1-83-21

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit 1, the enclosed supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,


C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/sdl/LETDD1

Enclosure

cc: Mr. R. C. DeYoung
NRC Document Control Desk

OFFICIAL COPY

IE22
11