



Carolina Power & Light Company

P.O. Box 101, New Hill, N.C. 27562
July 25, 1984

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 2900)
Atlanta, Georgia 30323

NRC-247

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1986 - 900,000 KW - UNIT 1
RAB EMERGENCY AIR CLEANING UNITS -
WELD DEFICIENCIES, ITEM 180

Dear Mr. O'Reilly:

On June 28, 1984, Mr. N. J. Chiangi notified the NRC (Mr. A. Hardin) of a potentially reportable item per the provisions of 10CFR50.55(e) and 10CFR, Part 21. The NRC was informed that weld deficiencies were identified in four RAB Emergency Air Cleaning Units supplied by CTI Nuclear, Inc.

CP&L is currently awaiting Ebasco to complete an analysis of the welded connections which were identified as deficient. It is projected that the analysis will be received and a report on the reportability of this item will be issued by August 30, 1984.

Thank you for your consideration in this matter.

Yours very truly,

R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/jam

Attachment

cc: Messrs. G. Maxwell/R. Prevatte (NRC-SHNPP)
Mr. R. C. DeYoung (NRC)

8408160416 840725
PDR ADOCK 05000400
S PDR

OFFICIAL COPY
GIVEN BY 2247

IE27 110