

# The Light company

Houston Lighting & Power

South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

April 13, 1992  
ST-HL-AE-4056  
File No.: T07.03  
10CFR50

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project Electric Generating Station  
Unit 2


Docket No. STN 50-499

Unit 2 Second Refueling Outage Inservice

Inspection Summary Report for Repairs and Replacements Addendum-1

In accordance with our letter ST-HL-AE-4035, dated March 16, 1992, enclosed is the Unit 2 second refueling outage (2RE02) Inservice Inspection Summary Report for Repairs and Replacements (Addendum -1) performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from completion of the first refueling outage (December 11, 1990) to completion of the second refueling outage (December 18, 1991).

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298.

  
William J. Jump  
Manager,  
Nuclear Licensing

SDP/amp

Attachments: Per Attached Index

9204210213 920413  
PDR ADDCK 05000499  
Q PDR

A Subsidiary of Houston Industries Incorporated

47

Houston Lighting & Power Company  
South Texas Project Electric Generating Station

ST-HL-AE-4056  
File No.: T07.03  
Page 2

cc:

Regional Administrator, Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

George Dick, Project Manager  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

J. I. Tapia  
Senior Resident Inspector  
c/o U. S. Nuclear Regulatory  
Commission  
P. O. Box 910  
Bay City, TX 77414

J. R. Newman, Esquire  
Newman & Holtzinger, P.C.  
1615 L Street, N.W.  
Washington, DC 20036

D. E. Ward/T. M. Puckett  
Central Power and Light Company  
P. O. Box 2121  
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee  
City of Austin  
Electric Utility Department  
P.O. Box 1088  
Austin, TX 78767

K. J. Fiedler/M. T. Hardt  
City Public Service Board  
P. O. Box 1771  
San Antonio, TX 78296

Rufus S. Scott  
Associate General Counsel  
Houston Lighting & Power Company  
P. O. Box 61867  
Houston, TX 77208

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339-3084

Dr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, NY 11713

D. K. Lacker  
Bureau of Radiation Control  
Texas Department of Health  
1100 West 49th Street  
Austin, TX 78756-3189

Revised 10/11/91

L4/NRC/

## INDEX OF ATTACHMENTS

1. Cover Sheet
2. 2RE02 Inservice Inspection Summary Report for Repairs and Replacements, Addendum 1.