


LOUISIANA
POWER & LIGHT

WATERFORD 3 SES • P.O. BOX B • KILLONA, LA 70066

September 14, 1984

W3P84-2548
A-3-A35.07.112
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



REFERENCE: LP&L Letter W3K84-1969 dated August 23, 1984.

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 112
"Design Changes Via Memoranda"
Fourth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on September 14, 1984.

At the present time, however, evaluations are continuing and scheduled to be completed in mid September. A Detailed Interim Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/TJG/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8409270653 840914
PDR ADOCK 05000382
S PDR

IE-27

1/0

Mr. John T. Collins
W3P84-2548
Page 2

cc: Mr. E.L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W.M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W.A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814